





pp. 58-59: General view of the north side. The house stands on the typical courtyard of wooden buildings in Riga. This page, above: View from the terrace. This page, below: Interior of the office on the third floor, p. 61: Site model. Image courtesy of the architect.

58~59頁:北側の全景。この家はリー州 の木造建築の典型的な中庭に建っている 本頁、上:テラスからの眺め。 本頁、1 3階のオフィス内観。61頁、上:敷地模型 Huilding is located on Miera Street, Riga, in a courtyard between two wooden buildings, characteristic of 19th century architecture in Riga. Building volume and layout outline with rounded corners correspond to the building from 1950's, which was impossible to preserve due to technical condition of constructions. The first floor of building is created as a relief concrete base on top of which two-storey wooden volume is located. This solution was determined by context of surrounding wooden buildings as well as functional differences of volumes first floor and basement floors as office premises, second and third floors as apartments). To provide necessary amount of daylight in all apartment areas, continuous staircase is located at building's firewall. Building is completed by fourth floor roof volume with terrace.

この建物はリーガ市内のミエラ通り沿いに 木造の建物で囲まれていすという文脈、ま ●丸くした建物のヴォリュームとレイアウ Jで仕上げられ、その上に木造の2層のヴォ が設けられている。 リュームを載せている。こうした解決策は、

Project title: House in the Courtyard Location: Miera Str. 52a, Riga, Latvia


Architect: Sudraba Arhitektura / Reinis Liepins Construction engineer: IG Kurbads

Credits and Data

Completed: 2008

■■し、19世紀のリーガの建築の特徴を備 たヴォリューム同士で機能が異なる(1階と ※ た2つの木造建造物のはざまに立つ。角 地下はオフィス、2階と3階は居住用アパー ト) という観点から決定された。共同住宅エ ▶の輪郭は、建造の技術条件のために保存 リア全体に日光を必要なだけとりこめるよ ●きなかった1950年代の建物のそれに相当 うに、建物の防火壁に連続して階段が設置 **する。建物の1階はコンクリート・レリー** されている。最上階の4階にはルーフテラス (松本晴子訳)






Sketch/スケッチ



Third floor plan/3階平面図



Ground floor plan (scale: 1/200)/地上階平面図(縮尺: 1/200)



Section (scale: 1/200)/新面図 (縮尺: 1/200)